

### AT32F402/405 device limitations

## Device identification

This errata sheet applies to ARTERY AT32F402/405 microcontrollers which is based on an ARM® 32-bit Cortex®-M4 core.

**Table 1. Device summary**

| Device       | Flash memory | Part number   |
|--------------|--------------|---|
| AT32F402/405 | 256 KB       | AT32F405RCT7, AT32F405RCT7-7,<br>AT32F405CCT7, AT32F405CCU7,<br>AT32F405KCU7-4, AT32F402RCT7,<br>AT32F402RCT7-7, AT32F402CCT7,<br>AT32F402CCU7, AT32F402KCU7-4, |
|              | 128 KB       | AT32F405RBT7, AT32F405RBT7-7,<br>AT32F405CBT7, AT32F405CBU7,<br>AT32F405KBU7-4, AT32F402RBT7,<br>AT32F402RBT7-7, AT32F402CBT7,<br>AT32F402CBU7, AT32F402KBU7-4, |

## Contents

|          |   |          |
|----------|---|----------|
| <b>1</b> | <b>AT32F402/405 device limitations .....</b>  | <b>4</b> |
| 1.1      | PWC.....  | 5        |
| 1.1.1    | PVM event generated after PVM enable when VDD is above PVM threshold .....            | 5        |
| 1.1.2    | Unable to wakeup Deepsleep mode after AHB frequency division .....                    | 5        |
| 1.1.3    | Higher power consumption in Deepsleep mode because of OTGHS PHY default setting ..... | 5        |
| 1.2      | ERTC .....  | 5        |
| 1.2.1    | Read/write ERTC occupies APB1 for 15 ERTC clock cycles .....                          | 5        |
| 1.3      | CRM.....  | 6        |
| 1.3.1    | CRM_BPDC/CRM_CTRLSTS registers limitations .....                                      | 6        |
| 1.4      | QSPI.....   | 7        |
| 1.4.1    | DMA P2M mode usage condition in QSPI command port mode.....                           | 7        |
| 1.4.2    | Excess dummy clock sent after read operation in QSPI command port mode.....           | 7        |
| 1.5      | GPIO .....  | 7        |
| 1.5.1    | PC13-related features unavailable during slower MCU power-on .....                    | 7        |
| 1.6      | CAN.....  | 8        |
| 1.6.1    | Fail to cancel mailbox transmit command when CAN bus disconnected .....               | 8        |
| <b>2</b> | <b>Document revision history .....</b>  | <b>9</b> |

## List of tables

|  |   |
|--|---|
| Table 1. Device summary .....                | 1 |
| Table 2. Summary of device limitations ..... | 4 |
| Table 3. Document revision history.....      | 9 |

## 1 AT32F402/405 device limitations

*Table 2* gives a list of limitations that have been identified so far on the AT32F402/405 devices.

**Table 2. Summary of device limitations**

| Sections | Description   |
|----------|---|
| 1.1 PWC  | 1.1.1 PVM event generated after PVM enable when VDD is above PVM threshold            |
|          | 1.1.2 Unable to wakeup Deepsleep mode after AHB frequency division                    |
|          | 1.1.3 Higher power consumption in Deepsleep mode because of OTGHS PHY default setting |
| 1.2 ERTC | 1.2.1 Read/write ERTC occupies APB1 for 15 ERTC clock cycles                          |
| 1.3 CRM  | 1.3.1 CRM_BPDC/CRM_CTRLSTS registers limitations                                      |
| 1.4 QSPI | 1.1.1 DMA P2M mode usage condition in QSPI command port mode                          |
|          | 1.1.2 Excess dummy clock sent after read operation in QSPI command port mode          |
| 1.5 GPIO | 1.2.1 PC13-related features unavailable during slower MCU power-on                    |
| 1.6 CAN  | 1.6.1 Fail to cancel mailbox transmit command when CAN bus disconnected               |

## 1.1 PWC

### 1.1.1 PVM event generated after PVM enable when VDD is above PVM threshold

- Description:  
Enabling PWC voltage monitoring feature while the VDD is greater than PVM threshold will trigger an unexpected PVM event.
- Workaround:  
Clear the unexpected PVM event during PVM initialization.

### 1.1.2 Unable to wakeup Deepsleep mode after AHB frequency division

- Description:  
After AHB frequency is divided, no wakeup sources can wake up Deepsleep mode.
- Workaround:  
Do not divide AHB frequency while using Deepsleep mode.  
Remove AHB frequency division before entering Deepsleep mode. Configure then the desired AHB frequency after waking up Deepsleep mode.

### 1.1.3 Higher power consumption in Deepsleep mode because of OTGHS PHY default setting

- Description:  
The device direct entry into Deepsleep mode may lead to power consumption of up to 3.5 mA.
- Workaround:  
Refer to PWC DEEPSLEEP DEMO to configure relevant registers.  
The demo is located at project\at\_start\_f402\examples\pwc\deepsleep\_ertc\_alarm

## 1.2 ERTC

### 1.2.1 Read/write ERTC occupies APB1 for 15 ERTC clock cycles

- Description:  
As reading/writing ERTC registers takes around 15 APB1 clock cycles to be synchronized with battery powered domain, APB1 is occupied and DMA transfer on APB1 also is halted during this period. After the completion of synchronization, APB1 is released automatically, and DMA transfer continues execution.
- Workaround:  
After ERTC initialization, users need minimize the times of writing ERTC registers provided that ERTC features can satisfy users' needs, in order to reduce its impact on system.

## 1.3 CRM

### 1.3.1 CRM\_BPDC/CRM\_CTRLSTS registers limitations

- Description:

Accessing CRM\_BPDC register and CRM\_CTRLSTS register may not work when the AHB domain is greater than 120 MHz.

- Workaround:

Accessing these registers is made possible when the AHB domain is no more than 120 MHz. This means that the maximum allowable frequency of the AHB domain while accessing these two registers is 120 MHz.

See reference code below:

```
/**
 * @brief  main function.
 * @param  none
 * @retval none
 */
int main(void)
{
    /*access the CRM_BPDC/CRM_CTRLSTS register here*/
    crm_ertc_clock_enable(TRUE);

    system_clock_config();

    ...
    while(1)
    {
        ...
    }
}
```

## 1.4 QSPI

### 1.4.1 DMA P2M mode usage condition in QSPI command port mode

- Description:  
When QSPI is configured in command port mode, a specific condition must be respected to use DMA P2M mode for data transfer, detailed as follows.
- Workaround:  
When QSPI is configured in command port mode, to use DMA P2M mode to transfer data, the MSIZE must select word format, and data size must be a multiple of 4.

### 1.4.2 Excess dummy clock sent after read operation in QSPI command port mode

- Description:  
When QSPI is configured in command port mode, after the completion of read access, an additional dummy clock will be sent, which has no impact on applications in most cases.
- Workaround:  
None.

## 1.5 GPIO

### 1.5.1 PC13-related features unavailable during slower MCU power-on

- Description:  
In the process of MCU being powered on at a slower rate, there is a possibility that PC13-related functions such as input/output, ERTC tamper detection are unavailable.
- Workaround:

Perform another system reset following this power on. See the reference code below:

```
if((CRM->ctrlsts_bit.porrstf == SET) && (CRM->ctrlsts_bit.swrstf == RESET))
{
    NVIC_SystemReset();
}
```

After above operation, software reset flag (SWRSTF) will be set. If the application program needs to perform corresponding operations based on SWRSTF bit, follow the procedures below:

- A. When the software reset flag and power-on reset flag are set simultaneously, it means that this is a system reset used to solve PC13 issues. Thus there is a need to clear all reset flags by calling relevant functions.
- B. When the software reset flag is set but power-on reset flag isn't, it indicates that this is a system reset performed by the program application layer for application processing.

## 1.6 CAN

### 1.6.1 Fail to cancel mailbox transmit command when CAN bus disconnected

- Description:

As a node for data transmission, if the following two conditions are both present for CAN, it is not possible to clear or cancel a transmit command in a mailbox within CAN error passive interrupt, causing that the to-be-sent message command has not been canceled during the period of CAN bus being disconnected, and such message would be retransmitted after CAN bus communication resumes.

The two conditions include:

1. CAN bus (CANH/L) is disconnected intentionally or accidentally
2. Automatic retransmission feature is enabled

- Workaround:

When a message failed to be sent out for several times, disable automatic retransmission feature when the following two conditions are met at the same time:

1. Error type is "Passive bit error"
2. Mailbox transmit state is "mailbox\_x transmit error"

Then re-activate auto retransmission feature in the subsequent CAN message transmit function.



## 2 Document revision history

Table 3. Document revision history

| Date       | Revision | Changes         |
|------------|----------|-----------------|
| 2023.08.03 | 2.0.0    | Initial release |

## IMPORTANT NOTICE – PLEASE READ CAREFULLY

Purchasers are solely responsible for the selection and use of ARTERY's products and services, and ARTERY assumes no liability whatsoever relating to the choice, selection or use of the ARTERY products and services described herein

No license, express or implied, to any intellectual property rights is granted under this document. If any part of this document deals with any third party products or services, it shall not be deemed a license granted by ARTERY for the use of such third party products or services, or any intellectual property contained therein, or considered as a warranty regarding the use in any manner of such third party products or services or any intellectual property contained therein.

Unless otherwise specified in ARTERY's terms and conditions of sale, ARTERY provides no warranties, express or implied, regarding the use and/or sale of ARTERY products, including but not limited to any implied warranties of merchantability, fitness for a particular purpose (and their equivalents under the laws of any jurisdiction), or infringement on any patent, copyright or other intellectual property right.

Purchasers hereby agree that ARTERY's products are not designed or authorized for use in: (A) any application with special requirements of safety such as life support and active implantable device, or system with functional safety requirements; (B) any aircraft application; (C) any aerospace application or environment; (D) any weapon application, and/or (E) or other uses where the failure of the device or product could result in personal injury, death, property damage. Purchasers' unauthorized use of them in the aforementioned applications, even if with a written notice, is solely at purchasers' risk, and Purchasers are solely responsible for meeting all legal and regulatory requirements in such use.

Resale of ARTERY products with provisions different from the statements and/or technical characteristics stated in this document shall immediately void any warranty grant by ARTERY for ARTERY's products or services described herein and shall not create or expand any liability of ARTERY in any manner whatsoever.

© 2023 Artery Technology -All rights reserved