

Release Notes for AT32L021 Firmware Library

V2.0.3-2024/04/08

1. Updated the procedure of how to enable the *_clock.c HEXT

V2.0.2-2024/03/01

1. Added LDO functions and its use method
2. Updated PVM threshold macro definition

V2.0.1-2024/01/19

1. Updated the method of calling the xx_interrupt_flag_get function in all Demos
2. Updated the systick initialization function in the systick interrupt demo
3. Updated some notes

V2.0.0-2024/01/11

1. Initial release of AT32L021 series firmware library